## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L22	1	(((oxide adj superconductor) with (metal\$4 near3 electrode) with (current adj lead) with (join\$4 or connect\$4) with (void or hole or defect por\$4)).clm.	US-PGPUB	OR	OZ	2008/04/13
L23	1	((oxide adj superconductor) same (metal§4 near3 electrode) same (current adj lead) same (join§4 or connect\$4 or interconnect\$4) same (void or hole or defect joor\$4)).clm.	US-PGPUB	OR	ON	2008/04/13
L24	3	((oxide adj superconductor) and (metal\$4 near3 electrode) and (current adj lead) and (join\$4 or connect\$4 or interconned\$4) and (void or hole or defect por\$4).clm.	US-PGPUB	OR	ON	2008/04/13 10:12
L25	2	24 not 23	US-PGPUB	OR	ON	2008/04/13 10:12
L26	1	((oxide adj superconductor) with (metal\$4 near3 electrode) with (join\$4 or connect\$4 or interconnect\$4) with (void or hole or defect por\$4)).clm.	US-PGPUB	OR	ON	2008/04/13

L27	T	((oxide adj superconductor) same (metal\$4 near3 electrode) same (join \$4 or connect\$4 or interconnect\$4) same (void or hole or defect por\$4)).clm.	US-PGPUB	OR	ON	2008/04/13 10:13
L28	5	((oxide adj superconductor) and (metal\$4 near3 electrode) and (join\$4 or connect\$4 or interconnect\$4) and (void or hole or defect por\$4)).clm.	US-PGPUB	OR	ON	2008/04/13 10:14
L29	2	28 not (24 or 23)	US-PGPUB	OR	ON	2008/04/13 10:14
L35	2	((oxide adj superconductor) and (metal\$4 near3 electrode) and (current adj lead) and (join\$4 or connect\$4 or interconnect\$4) and (cross adj section or surface) and (area)). clm.	US-PGPUB	OR	ON	2008/04/13 10:17
L38	1	((oxide adj superconductor) and (metal\$4 near3 electrode) and (join\$4 or connect\$4 or interconnect\$4) and (section\$2 or surface) and (area) and (over \$1lap\$4)).clm.	US-PGPUB	OR	ON	2008/04/13 10:28

<sup>4/13/08 10:29:33</sup> AM

C:\ Documents and Settings\ ipatel\ My Documents\ EAST\ Workspaces

<sup>\10771381</sup>APR08.wsp